

5. Connect the plotter / engraver to your computer and switch on.

The “Found New Hardware Wizard” starts. When asked „Can windows connect to Windows Update to search for the software?“, choose “No, not this time”.



6. When asked “What do you want the wizard to do?” Choose “Install the software automatically (Recommended)”.



7. When the message “The software you are installing... has not passed Windows Logo testing...” appears, click on “Continue Anyway”.



8. Click on the “Finish” button to complete the driver installation.



The plotter / engraver can now be used. You can sign in with your user account.

4. Windows 2000

1. Sign in as an administrator. Open the Folder **"Psetup"** and start the program **"psetup.exe"**
2. A message window will remind you to keep the plotter / engraver switched off. Click on **"OK"** to start the pre- installation.



3. **During the installation of the plotter / engraver software the message window "Digital signature not found" appears.**

Answer the question **"Do you want to continue the installation?"** with **"Yes"**.



4. When the pre- installation is finished, you will be notified that you can now connect and switch on your plotting or engraving device. Acknowledge with **"OK"**.



5. Connect the plotter / engraver to your computer and switch it on.
6. The message window **“Digital signature not found”** will appear again. Answer with **“Yes”**.



The plotter / engraver can now be used. You can sign in with your normal user account.